



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # N08812  
SPO Map 08-09-33  
Hundred Newcastle  
Quad Newark East  
Other Parcel:1002800014

1. HISTORIC NAME/FUNCTION: Albert and Sylvia Jones House
2. ADDRESS/LOCATION: 142 E Main Street, Newark, Delaware 19702
3. TOWN/NEAREST TOWN: Christiana vicinity?
4. MAIN TYPE OF RESOURCE: building  structure  site  object   
landscape  district
5. MAIN FUNCTION OF PROPERTY: Single-family dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):  
SR 1 Road Widening

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
0	CRS 3 Secondary Building Form	N/A
0	CRS 4 Archaeological Site Form	N/A
0	CRS 5 Structure (Building-Like) Form	N/A
0	CRS 6 Structure (Land Feature) Form	N/A
0	CRS 7 Object Form	N/A
0	CRS 8 Landscape Elements Form	N/A
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	N/A

8. SURVEYOR INFORMATION:

Surveyor name: Patti Kuhn/Sarah Groesbeck

Principal Investigator name: Patti Kuhn

Principal Investigator signature: *Patti Kuhn*

Organization: The Louis Berger Group Date: June 2012

9. OTHER NOTES OR OBSERVATIONS:

CRS# N08812

The property is also being evaluated or reassessed for its National Register eligibility or listing status. This evaluation assessment is triggered by the federal undertaking initiated by DeIDOT and the Federal Highway Administration as part of the SR 1 Roth Bridge to Interstate 95, Capacity Improvement Project (T200511001; Federal Aid NH-N067(26)). Further referenced information on this property as well as other in the vicinity, can be seen in the Architectural Evaluation entitled, "Architectural Survey Report, SR 1 Widening, New Castle County, Delaware."

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
  - 1600-1750∇ Contact Period (Native American)
  - 1630-1730∇ Exploration and Frontier Settlement
  - 1730-1770∇ Intensified and Durable Occupation
  - 1770-1830∇ Early Industrialization
  - 1830-1880∇ Industrialization and Early Urbanization
  - 1880-1940∇ Urbanization and Early Suburbanization
  - 1940-1960∇ Suburbanization and Early Ex-urbanization
- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)
- c) Historic period theme(s)
- |  |   |
|--|---|
| <input type="checkbox"/> Agriculture           | <input type="checkbox"/> Transportation and Communication                         |
| <input type="checkbox"/> Forestry              | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes   |
| <input type="checkbox"/> Trapping/Hunting      | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying      | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering     | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing         | <input type="checkbox"/> Education  |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations                                  |
| <input type="checkbox"/> Finance               | <input type="checkbox"/> Occupational Organizations                               |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events                   |



CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # N08812.001

1. ADDRESS/LOCATION: 142 E Main Street, Newark, Delaware 19702

2. FUNCTION(S): historic Single-family dwelling current Single-family dwelling

3. YEAR BUILT: 1951 CIRCA?:  ARCHITECT/BUILDER: Unknown

4. STYLE OR FLOOR PLAN: 2-story Massed Form

5. INTEGRITY: original site  moved

<u>if moved, from where</u>	<u>other location's CRS #</u>	<u>year</u>
N/A	N/A	
N/A	N/A	

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. North wing	Ca.1955-1964
b. N/A	N/A

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangle Stories: 2  
Additions: N wing

b Structural system (if known): masonry

c. Foundation: materials: not visible  
basement: full  partial  not visible  no basement

d. Exterior walls (original if visible& any subsequent coverings):

e. Roof: shape: gable  
materials: asphalt shingles  
cornice: N/A  
dormers: N/A  
chimney: location(s): exterior end S elevation with stucco facing

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: East

- 1) Bays 5
- 2) Windows 6

fenestration 1<sup>st</sup> floor - 1 bay S wing, 1 picture window bay with sidelights on main block, 2 bays N wing; 2<sup>nd</sup> floor - 2 regular on main block

type 6/6 double-hung wood sash, 1/1 double-hung metal sash, picture window  
trim N/A  
shutters N/A

**Facade (cont'd)**

- 3) **Door(s)** 1  
     **location** N end of main block  
     **type** single-leaf  
     **trim** N/A
- 4) **Porch(es)** 1 bay gable-front porch w/ wood post supports and concrete foundation

**b. Side: Direction: North**

- 1) **Bays** 2
- 2) **Windows** 4  
     **fenestration** 1 small on 2<sup>nd</sup> story main block; 1 bay 1<sup>st</sup> floor of north wing & 2 bay 2<sup>nd</sup> floor  
     **type** 8/8 double-hung wood sash on 1<sup>st</sup> story & 6/6 on 2<sup>nd</sup> story; 3/3 on main block  
     **trim** N/A  
     **shutters** N/A
- 3) **Door(s)** N/A  
     **location** N/A  
     **type** N/A  
     **trim** N/A
- 4) **Porch(es)** N/A

**c. Side: Direction: South**

- 1) **Bays** not visible
- 2) **Windows** not visible  
     **fenestration** not visible  
     **type** not visible  
     **trim** not visible  
     **shutters** not visible
- 3) **Door(s)** not visible  
     **location** not visible  
     **type** not visible  
     **trim** not visible
- 4) **Porch(es)** not visible


**d. Rear: Direction: W**

- 1) **Bays** not visible
- 2) **Windows** not visible  
     **fenestration** not visible  
     **type** not visible  
     **trim** not visible  
     **shutters** not visible
- 3) **Door(s)** not visible  
     **location** not visible  
     **type** not visible  
     **trim** not visible
- 4) **Porch(es)** not visible

9. **INTERIOR:** not accessible

10. **LANDSCAPING:** The property contains approximately nine-and-one-half acres of land. A paved driveway runs from the road, just north of the dwelling. The majority of the property is heavily wooded, with a small grassy clearing for the dwelling. Foundation plantings are located along the north elevation of the house.

11. **OTHER COMMENTS:** N/A



CULTURAL RESOURCE SURVEY

CRS # N08812

MAP FORM

1. ADDRESS/LOCATION: 142 E Main Street, Newark Delaware, 19702


2. NOT FOR PUBLICATION  reason: \_\_\_\_\_

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # N08812      Date 5/21/2012      Photo Roll # n/a      Surveyor S Groesbeck & P Kuhn

Description Façade (east elevation) and north elevation of main building (.001) looking southwest

Negative location (if other than SHPO) \_\_\_\_\_

Attach contact print(s):

