



Figure 1- ADA parking facilities at the Wolfe Neck Road trailhead



Figure 2- Parking facilities and landscaping at the Wolfe Neck Road trailhead



Figure 3- Looking NE at access trail from the Wolfe Neck Road trailhead



Figure 4- Self payment box at trailhead



Figure 5- UTAP information strip at trailhead kiosk



Figure 6- Informational signage and trash bags provided at trailhead



Figure 7- Pet owner clean-up bags provided at trailhead



Figure 8- Collapsible bollards provided for restricted access from the Trailhead parking facility onto the access trail



Figure 9- ADA parking facilities and restroom facilities provided at the Wolfe Neck Road trailhead



Figure 10- Roadway striping and signage at rail-trail crossing on Wolfe Neck Road




Figure 11- Looking NW from Wolfe Neck Road at rail-trail collapsible bollards, signage, and fencing



Figure 12- Looking SE across Wolfe Neck Road crossing



Figure 13- DNREC collapsible bollards for rail-trail facilities



Figure 14- Looking NW from Hebron Road in Rehoboth at the south terminus of the Junction & Breakwater Trail



Figure 15- Looking SE from the Holland Glade Road crossing



Figure 16- Looking NW from the Holland Glade Road crossing